# UTAH DEPARTMENT OF TRANSPORTATION

TECHNICAL BULLETIN MT-05.03 January 19, 2005

# **Pre-cast Concrete**

Because precast concrete products typically are produced in a controlled environment, they exhibit high quality and uniformity. Precast concrete products arrive at the jobsite ready to install. There is no need to order raw materials such as reinforcing steel and concrete, and there is no need to expend time setting up forms, placing concrete or waiting for the concrete to cure.

<u>Pre-Qualification:</u> Precast concrete items used on UDOT projects are required to be from pre-qualified suppliers. Suppliers are qualified through the Prestressed/Precast Concrete Quality Management Plan. This plan is managed and



maintained by UDOT Central Materials Lab. The Plant Certification Program assures a uniform high degree of excellence in plant facilities, production, processes, and quality control operations. One standard of quality is set for all precast concrete products, effectively leveling the playing field for all plants wishing to supply products to the project. A listing of precast concrete qualified suppliers can be found at: <a href="http://www.dot.state.ut.us/index.php/m=c/tid=417">http://www.dot.state.ut.us/index.php/m=c/tid=417</a>

Acceptance Procedures: All precast concrete suppliers are required to maintain current certification through the National Precast Concrete Association (NPCA). The Central Materials Lab also performs one plant inspection per year to review and verify NPCA certification, as well as other requirements.

## FURTHER INFORMATION

### UDOT CONTACTS

Tim Biel, Engineer for Materials, (801) 965-4859, tbiel@utah.gov
Bill Lawrence, UDOT Concrete Engineer, (801) 965-4560, Billlawrence@utah.gov
Robert Winters, UDOT Materials Tech, (801) 633-6269, Robertwinters@utah.gov

#### OTHER CONTACT

National Precast Concrete Association, 10333 N. Meridian St., Suite 272, Indianapolis, IN 46290

Main: 317-571-9500

Toll Free: 800-366-7731

Fax: 317-571-0041

http://www.precast.org/